

Refrigerant condensers

Options and accessories

Standby pump



Installing a standby pump **guarantees year-round reliable operation** – takes over in event of failure.

Models VXC 14, VXC 18, VXC 25, VXC 28, VXC 36, VXC 45, VXC 52, VXC 59, VXC 65, VXC 72, VXC 86, VXC 97, VXC 110, VXC 125, VXC 135, VXC 150, VXC 166, VXC 185, VXC 205, VXC C220, VXC C250, VXC C265, VXC C287, VXC C325, VXC C340, VXC C380, VXC C408, VXC C426, VXC 221, VXC 250, VXC 265, VXC S288, VXC S300, VXC S328, VXC S350, VXC 403, VXC S429, VXC S455, VXC S482, VXC S504, VXC 357, VXC 399, VXC 454, VXC 562, VXC 620, VXC 680, VXC 495, VXC 516, VXC 715, VXC 772 and VXC 804 can have a standby pump, located on the opposite side.

For VXC S576, VXC S600, VXC S656, VXC S700, VXC S806, VXC S858, VXC S910, VXC S964, VXC S1010, VXC 990, VXC 1032, VXC 1430, VXC 1544, VXC 1608, VXC 714, VXC 798, VXC 908, VXC 1124, VXC 1240 and VXC 1360 standby pumps are not possible.

Want to benefit from a standby pump? Contact your <u>local BAC representative</u>.